

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

GX994
NNW
> 1
1.303 mi.
6881 ft.

VS #6424
86TH & WEST OF 25TH AVE
BROOKLYN, NY

NY Spills S107787979
N/A

Site 1 of 3 in cluster GX

Relative:
Higher

Actual:
12 ft.

SPILLS:

Name: VS #6424
Address: 86TH & WEST OF 25TH AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0601421 / 2006-06-14
Facility ID: 0601421
Facility Type: ER
DER Facility ID: 313823
Site ID: 363650
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2006-05-08
Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 2006-05-08
CID: 444

Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2006-05-08
Spill Record Last Update: 2006-07-17
Spiller Name: ERT DESK'
Spiller Company: VS #6424
Spiller Address: 86TH & WEST OF 25TH AVE
Spiller Company: 001
Contact Name: ERT DESK'
DEC Memo: "06/14/06 - See e-docs for Con Ed report detailing cleanup and

closure. 08-MAY-2006 12:50 HRS. TRANSFORMER VS6424 ON FEEDER 7B44 - UNIT BELOW MIN. AND APPEARS TO BE LEAKING. FOUND 6 GALS OF DIELECTRIC FEEDER FLUID ON 20 GALS OF WATER. See e-docs. (JHO)"
Remarks: "no sewers,waterways, no private property: coned # 164157"

All Materials:

Site ID: 363650
Operable Unit ID: 1121699
Operable Unit: 01
Material ID: 2111199
Material Code: 0541A
Material Name: dielectric fluid
Case No.: Not reported
Material FA: Petroleum
Quantity: 6.00
Units: G
Recovered: .00
Oxygenate: Not reported